

WARNING

Name of the Mine	Prakasham Khani Opencast Mine
Name of the Owner	M/s Singareni Collieries Company Ltd.
Date and time of accident	26.12.2016, 03.45 hours
No. of persons killed	One
Prima facie cause of the accident	While a 100T dumper was being driven negligently on a haul road, it's cabin protruded into the left side rear bucket of another 100T dumper parked aside on the haul road due to which the person driving the 100T dumper succumbed instantaneously.

TAKE ACTION TO PREVENT SUCH TYPE OF ACCIDENT IN FUTURE