

WARNING

Name of the Mine	Pali Underground Mine
Owner of the Mine	M/s South Eastern Coalfields Ltd.
Date and Time of Accident	28.11.2016, 1945 hrs
Number of persons killed	1 (One)
Number of persons seriously injured	Nil
Prime facie cause of the accident	While a Sirdar and Shot-firer were inspecting the blasted face in a depillaring district of a belowground coal mine, suddenly fall in the goaf extended into the nearby gallery upto about 12m and trapped the Sirdar who succumbed to injuries instantly whereas the Shot-firer escaped unhurt.

TAKE TIMELY ACTION TO PREVENT SUCH TYPE OF ACCIDENT IN FUTURE