



WARNING

Name of the Mine	Dhori Khas Colliery, Dist. Bokaro
Name of the Owner	M/s CCL
Date & Time of the Accident	14.09.2018; 1330Hrs
No. of persons killed	One
	
Prima facie cause of the Accident	While a hydraulic bolter machine was being shifted by a contractual worker belowground after roof bolting work without the use of proper Personal Protective Equipment (PPE) got electric shock due to leakage current in the body of the bolting machine and fell down which proved fatal afterwards.