

Sl No.	Details	
(A)	Name of the Mine	Kanchan Opencast Mine
(B)	Owner of the Mine	M/s South Eastern Coalfields Ltd.
(C)	Date and Time of Accident	02.05.2018 , 2230 hrs
(D)	Number of persons killed	1 (One)
(E)	Number of persons seriously injured	Nil
(F)	Photographs (maximums two numbers)	As the accident occurred in underground, no photographs were taken.
(G)	Prime facie cause of the accident	While a light motor vehicle carrying a helper was going down on the haul road of an opencast coal mine for refueling in diesel operated equipment, the driver lost control over the vehicle due to over speed and resulting into toppling of the vehicle; meanwhile the helper jumped out from the vehicle, inflicting serious injuries to him which he succumbed later on and the driver escaped unhurt.