

WARNING

| | |
|-----------------------------------|---|
| Name of the Mine | Workover Mine, NHK#547, Rig RG-E |
| Name of the Owner | M/s Oil India Ltd. |
| Date and time of accident | 21.11.2016, 13.30 hours |
| No. of persons killed | One |
| Prima facie cause of the accident | While rig mast up job in a workover oil mine was being done, a person fixing the joint bolts sitting on the Y-type bracket was hit by the falling elevator link of the travelling block, thus sustaining internal bodily injuries, which proved fatal during medical treatment at hospital. |

TAKE ACTION TO PREVENT SUCH TYPE OF ACCIDENT IN FUTURE