

Name of the mine	Hirakhand Bundia Mine
Owner of the Mine	M/s Mahanadi Coalfields Limited
Date and time of the accident	14.01.2020 & 11.30 Hrs
Number of persons Killed	0
Number of persons Seriously Injured	1
Prima facie cause of the accident	While shots were fired at a junction in development district of an underground coal mine, mining sirdar of the district inadvertently entered the blasting area and was hit by blasting projectiles inflicting serious bodily injuries to him
Photographs (Maximum 2 nos)	