


WARNING

Name of the Mine	Lignite Mine – II
Owner of the Mine	NLC India Ltd.
Date and time of accident	02/03/2018 Time: 10:00 Hrs
Number of persons killed	01 (One)
Number of persons seriously injured	NIL
Photographs	 <p>The top photograph shows a wide, muddy brown river or sump water body extending to the horizon. In the foreground, there is a steep, dark earthen bank with several large, dark pipes or hoses running along its edge. A metal structure, possibly a gate or part of a conveyor system, is visible on the right side of the bank. The bottom photograph shows a closer view of the same area, focusing on a large, blue industrial structure, likely a pump or generator, situated on the earthen bank. The pipes and hoses are more prominent in this view, and the muddy water is visible in the background.</p>
Prime facie cause of the accident	Drowning Case (Drowning in Sump Water)