


WARNING

Name of the Mine	Baghsuri Quartz & Feldspar Mine, (ML NO -347/2005)
Name of the Owner	Shri Shiv Prasad Kabra
Date and time of accident	19.05.2018
No. of Persons killed	One
	
Prima Facie Cause of the accident	“While three daily wages workers were engaged in loading of segregated quartz and feldspar from spoil dump located nearby but outside leasehold area of the mine, they were hit by reversing tractor due to which they fell into a ditch of depth about 1.5 m near to the toe of spoil dump and struck with stone boulders inflicting serious injuries to all ,one of them was declared brought dead in hospital and others two were survived with serious bodily injuries.”

TAKE ACTION TO PREVENT SUCH TYPE OF ACCIDENT IN FUTURE