

WARNING

Name of the Mine	Ostapal Chromite Mine
Name of the Owner	M/s Ferro Alloys Corpn. Ltd.
Date and time of accident	24.01.2017, 09.00 hours
No. of persons killed	One
Prima facie cause of the accident	While connecting flexible water hose to the pipe at water tank, suddenly all the side walls of the water tank collapsed and one of its side wall fell down on the deceased.

TAKE ACTION TO PREVENT SUCH TYPE OF ACCIDENT IN FUTURE