


## **ACCIDENT ALERT**

Details	
Name of Mine	Churcha Mine (R.O.)
Owner of the Mine	M/s SECL
Date and time of accident	<b>29.05.2020 (3<sup>rd</sup> Shift) (Time: 01.10 hrs) on 30.05.2020</b>
Number of Persons Killed	01 (One)
Number of persons seriously injured	00 (Nil)
Photographs (maximums two numbers)	
Prima facie cause of accident	<p><b>0334 – Transportation machinery (Conveyors):</b></p> <p>“While a timber mistry, authorized to work as conveyor operator, was trying to remove a coal piece stuck near discharge drum of a running belt conveyor with a hand shovel in a belowground coal mine, he was pulled and trapped between the discharge drum and the chute side plate and received multiple injuries to which he succumbed at the spot”.</p>