


ACCIDENT ALERT

Details	
Name of Mine	Kurasia Underground Mine
Owner of the Mine	M/s SECL
Date and time of accident	23.06.2020 (3rd Shift) (Time: 01.45 hrs)
Number of Persons Killed	01
Number of persons seriously injured	00
Photographs (maximums two numbers)	
Prime facie cause of accident	0555(Explosives) “While an UDM (Universal Drilling Machine) operator was drilling holes with UDM at the floor near a split face of a depillaring panel in an underground mine, the drill rod of the UDM accidentally holed into a misfired shot of previous shift causing it to explode, in which an UDM helper who was present near the face was hit by the projectiles of the explosion receiving multiple injuries, to which he succumbed on the way to hospital”.