





## भारत सरकार / Government of India श्रम एवं रोजगार मंत्रालय / Ministry of Labour & Employment खान सुरक्षा महा-निदेशालय / Directorate General of Mines Safety

DGMS Safety Alert: 05/2024 Dhanbad, dated 13.05.2024

## SUBJECT: FATAL ACCIDENT DUE TO SIDE FALL OF SIDES IN A MARBLE QUARRY

1. Name of Mine : Sawar Marble Mine (ML. No. 285/1991)

2. Name of Owner : Shri Rajendra Kumar Agrawal

District : Kekri State : Rajasthan Mineral mined: : Marble

4. Date and time : 10.04.2024 at about 11:00 Hrs

ofaccident

3.

5. Place of bottom bench at a depth of about 60m from surface

accident

6. Brief Cause : While two persons were engaged on a marble bottom bench at a depth

of about 60m from surface on eastern side of an opencast mine, suddenly a part of highwall rock mass measuring about 20m (length)  $\times$  24m (height)  $\times$  2.5m (thickness) failed and fell over on bottom bench causing fatal injury

to one person.

7. Killed: : Name: Hanuta Ram, Age: 1yrs

Designation: Wire saw helper Experience on the job: 02 days

8. Seriously Injured: : Nil

9. Photographs





Fall of bench

Pleace of accident

## 10. **Best Practices:**

- 1 Sides in an opencast working shall be adequately benched, sloped and secured so as to prevent danger from fall of sides.
- 2 Do not allow any person to work unless the condition of the place is ascertained to be safe by a competent supervisor accompanied by such assistant as he requires.

Safety Alert, a tool utilized by DGMS, informs the mining industry about potential safety issues and offers recommendations to prevent such incident.