



भारत सरकार/Govt. of India श्रम एवं रोजगार मंत्रालय/Ministry of Labour & Employment खान सुरक्षा महाननदेशालय/Directorate General of Mines Safety



SAFETY ALERT: 12/2024Dhanbad, dated06.06.2024SUBJECT: Fatal accident occurred on 09.01.2024 due to Fall of Person from height while
cleaning for preparing drilling area at the top of a high bench at Daharra Stone Mine Of M/S.
Shri Abhishek MishraShri Abhishek Mishra

		1	
1.	Name of Mine	:	Daharra Stone Mine (Gata No. 339 Khand No. 40 (New) 09 (Old))
2	Name of Owner	:	Shri Abhishek Mishra
2.	District	:	Mahoba
	State	:	Uttar Pradesh
3.	Mineral	:	Stone
4.	Date and time of accident	:	09.01.2024 at about 09:30 Hrs.
5	Place of accident	:	At the edge of the northern side bench of the mine
6	Killed	:	Name: Dhaniram, Designation: Driller, Age: 50 Years Experience: 01 Years
7.	Seriously Injured	:	Nil
8.	Brief Cause	:	While a person was cleaning for preparing drilling area for drilling short holes on top of a bench of about 38 m in height, he slipped and fell down resulting serious bodily injuries to which he succumbed .
9.	Sketches showing the accident:		



Best Practices

10.

- 1. Do not allow any persons to work at height /edge of the benches from where there is a risk of fall from height he is provided health safety life.
 - 2. Before deploying persons at the top of bench edge, see that the ground is stable.
 - 3. Provide adequate berms at all top edges of benches.
 - 4. Prepare and implement adequate SOPs to work near top edges of benches.
 - 5. Do not deploy inexperienced and untrained persons is the mine.
- 6. Educate the workers and the supervisors on risk assessment / job safety analysis before starting the work.